

PROJECT PROFILE



Installed Product :

MES100 Moisture Vapor Control System

Site Conditions :

At the Boeing Interior Mockup Center in Renton, Washington, there was moisture vapor emission problem affecting 14,000 square feet of floor space. Floor Seal Technology, Inc. was called in to correct the problem.

To remediate the problem, we installed our MES100™ Vapor Emission & Alkalinity Control System.

After our moisture system was installed, the final flooring was installed successfully.

