

XES, Inc.

The Xerox Engineering System Company
5853 Rue Ferrari
San Jose, California 95138

From: Don Kesner, Facilities Supervisor

Subject: Floor Seal Technology

Date: August 16, 1994

In April of 1992, Garland Floors installed approximately 50,000 square feet of ESD epoxy floor coating in our facility. The coating began to bubble and delaminate all over the floor in about 2 or 3 days.

After investigating all of the available sealers, they chose to use Floor Seal Technology, (FST), and their Fiber Membrane System.

The old floor coating was removed, and replaced with the membrane system over a 2 week period. After the installation, there were 4 or 5 small areas that delaminated again. FST pointed them out to us and corrected them over the next two weekends.

Over the past two years, FST has monitored the floor and repaired any found problems without being called in by Xerox. All of their work was scheduled in the off hours, causing no interruptions to our production activities. There is heavy forklift activity in most of these areas.

I would personally recommend Floor Seal Technology and their system to anyone attempting to combat a flooring moisture problem.

Sincerely,

Don Kesner

cc: Bill Clyne