

Marshall Industries

9320 Telestar Avenue
El Monte, California 91731

March 15, 1995

To Whom It May Concern:

In 1992 we began installing epoxy floors at our El Monte facility. We installed approximately 100,000 square feet during a one year period, but after installing the first phase, we began to have failures due to high levels of moisture vapor in our concrete floors.

The epoxy floor contractor, recommended Floor Seal Technology of San Jose to help correct a moisture problem. Floor Seal Technology first replaced a few 20' x 20' square patches in our forklift lane and then replaced a 10,000 square foot floor in our storage room. We were so pleased with the results of their combined techniques and job-site professionalism that we continued using their services on an additional 1,000 square feet in the warehouse, 8,000 square feet in an assembly room, and on a 100' corridor with a high built quartz floor on top.

I recommend Floor Seal Technology because of their workmanship and because of the professional manner that they demonstrated in every phase of the job. They also have stood behind their work and their warranty.

Sincerely,

Anthony W. Brannan
Facilities Manager