

Turner Construction Company



18600 S. Figueroa Street  
Carson, CA, 90248

September 20, 2012

Bill Clyne  
Floor Seal Technology, Inc.  
1005 Ames Ave.  
Milpitas, CA 95035

**RE: Re: Kaiser Carson Medical Offices**  
**Project Number: 120556**  
Kaiser Carson MOB Leveling

Dear Bill:

I wanted to let you know how well the Floor Seal Technology PowerPump System worked at our Kaiser Carson project.

Once the building was gutted, it was discovered that the second floor slab was severely cracked, in addition to having significant leveling and elevation issues. We contacted Floor Seal Technology to provide a solution that leveled the deck and prevented the cracks from showing in the finished flooring. The PowerPump System was the recommended solution. Floor Seal Technology designed a testing methodology to ensure that the system would not telegraph cracks through to the finished floor and to show the flatness achievable. Once the test proved successful, Floor Seal Technology got the notice to proceed and began the work on Thursday. Nearly 50,000 square feet was bead blasted, primed with your crack suppression system and topped with self-leveling cement by Tuesday the following week using the PowerPump System.

Your team overcame every obstacle and completed your work on schedule. The final floor was flat and smooth with no cracking even after the walls were installed. We are recommending and intend to use the same system on our next project.

Best regards,

Ed Kustanovich  
Senior Project Superintendent  
Turner Construction Company